

FLASH REPORT

This report is intended to provide initial external notification that an incident or high potential event has occurred.

RIMS REFERENCE NUMBER: HSIN2821

		CATEGORY	CLASSIFICATION
		INJURY	FATALITY
MINE SITE	Africa, Tanzania	ILLNESS	LOST TIME
LOCATION	North Mara,	PROPERTY DAMAGE	X RESTRICTED WORK
DEPARTMENT	Mining	PRODUCTION LOSS	MEDICAL TREATMENT
DATE	18 February 2013	NEAR MISS	MINOR
TIME	09h55	OTHER	HIGH POTENTIAL X
		IMMEDIATE REPORT	

INCIDENT DESCRIPTION:

On February 18th, 2013 at approximately 9h:55, an unqualified and unauthorized contractor worker employed as a dump truck spotter was working at the south end of the tailings storage facility. He took it upon himself to mount a 330 Cat Excavator and move it. While moving the machine he also swung it to his right where the bucket came into contact with a nearby mechanics light vehicle. There were no injuries. The light vehicle's undercarriage, framework and body were extensively damaged.

IMMEDIATE ACTIONS TAKEN:

- The incident was reported immediately reported to Supervision and Management
- The incident scene was isolated.
- The employee fled the scene immediately after the incident.
- The investigation was initiated

Photographs:

